FOR QUALITY & EXCELLENCE IN HIGHER EDUCATION
Accredited by NAAC

BANGALORE UNIVERSITY
DEPARTMENT OF CIVIL ENGINEERING

Phone Off: 080-22961935 / 1946
E-mail: centrans9@gmail.com

JNANA BHARATHI
BANGALORE - 560 056

BUB/CTE/2014-15

DATE: 17-04-2015

1. TEST REPORT ON CEMENT CONCRETE CUBES:

Sub: Testing of Concrete Cubes (07 days Compressive Strength)
{Project*:Construction of rain water Harvesting (main tank) to Govt School Building at Doddabommasandra and Ramachandrapura Community Building at Ramachandrapura and Yelumandamma Badavane in Ward no. 10 Vidyaranyapura Sub-Division.}

Ref.: Letter No. Testing/BUB/2014-15, dated 17-04-2015

Sample supplied to lab by: Sri.K.Shankarreddy, Contractor, Bangalore.

Report required for: Assistant Executive Engineer, Vidyaranyapura Sub-Division. BBMP, Bangalore.

RESULTS OF COMPRESSIVE STRENGTH ON CEMENT CONCRETE

CUBE SPECIMENS

Dimensions of Specimen : 150 X 150 X 150mm

Grade of Concrete* : M_{20}

TABLE 1.1 :

Sl No	Location/ Identification *	Date of Casting*	Date of Testing	Age in Days	C/S Area in Mm^2	Maximum Load in K.N	Compressive Strength (N/mm^2)	Avg. Value
1	001	10-04-15	17-04-15	07	22500	400	17.77	**17.62**
	002	"	"	"	"	390	17.33	
	003	"	"	"	"	400	17.77	

* As furnished by Client.
The Results relate only to the items tested.

Accepted

Page No. 1/1,

G.R. HARISH
Professor
Department of Civil Engineering
Jnana Bharathi Campus
BANGALORE UNIVERSITY
Bangalore-560 056.

Dr. MANJESH .L
ME (Civil Engg) Ph D MISTE.MIRC
Associate Professor
Department of Civil Engineering
Bangalore University Jnanabharathi Campus
BANGALORE- 560 056
e- mail. manjeshl@yahoo.com

FOR QUALITY & EXCELLENCE IN HIGHER EDUCATION
Accredited by NAAC

BANGALORE UNIVERSITY
DEPARTMENT OF CIVIL ENGINEERING

Phone Off: 080-22961935 / 1946
E-mail: centrans9@gmail.com

JNANA BHARATHI
BANGALORE - 560 056

BUB/CTE/2014-15/ **Date: 27-03-2015**

1. TEST REPORT ON REINFORCEMENT STEEL :

Sub: Testing of Reinforcement Steel of diameter 10mm.
{Project*:Construction of rain water Harvesting (main tank) to Govt School Building at Doddabommasandra and Ramachandrapura Community Building at Ramachandrapura and Yelumandamma Badavane in Ward no. 10 Vidyaranyapura Sub-Division.}

Ref.: Letter No. Testing/BUB/2014-15, dated 24-03-2015

Sample supplied to lab by: Sri.K.Shankarreddy, Contractor, Bangalore.

Report required for: Assistant Executive Engineer, Vidyaranyapura Sub-Division. BBMP, Bangalore.

TABLE – 1

SL No	Details	For 10mm	
		Test Results	Min Req as per IS 1786-2008
01	Observed diameter of bar	**10.0mm**	10.0mm
02	Observed Wt/m Length **Kg/m**	**0.622**	0.567
03	Proof stress/Yield stress, fy , **N/mm^2**	**548.0**	500.0
04	Bend/ Re bend Test	**Ok**	---
05	Percentage of Elongation, %	**22.10**	12.00
06	Ultimate Tensile Strength **N/mm^2**	**625.0**	545.0

*As furnished by Client.
The Results relate only to the items tested.

Accepted

G.R. HARISH
Professor
Department of Civil Engineering
Jnana Bharathi Campus
BANGALORE UNIVERSITY
Bangalore-560 056.

27/3/2015

Dr. MANJESH .L
ME (Civil Engg) Ph D MISTE.MIRC
Associate Professor
Department of Civil Engineering
Bangalore University Jnanabharathi Campus
BANGALORE- 560 056
e- mail. manjeshl@yahoo.com

FOR QUALITY & EXCELLENCE IN HIGHER EDUCATION
Accredited by NAAC

BANGALORE UNIVERSITY
DEPARTMENT OF CIVIL ENGINEERING

Phone Off: 080-22961935 / 1946
E-mail: centrans9@gmail.com

JNANA BHARATHI
BANGALORE - 560 056

BUB/CTE/2014-15/ **Date: 04-04-2015**

1. TEST REPORT ON CEMENT:

Sub: Testing of 53 Grade Cement Sample (IS 12269-1987).
{Project*:Construction of rain water Harvesting (main tank) to Govt School Building at Doddabommasandra and Ramachandrapura Community Building at Ramachandrapura and Yelumandamma Badavane in Ward no. 10 Vidyaranyapura Sub-Division.}
Ref.: Letter No. Testing/BUB/2014-15, dated 24-03-2015
Sample supplied to lab by: Sri.K.Shankarreddy, Contractor, Bangalore.
Report required for: Assistant Executive Engineer, Vidyaranyapura Sub-Division. BBMP, Bangalore.

PHYSICAL TESTS ON CEMENT

Brand* : Birla Grade * : 53
Type * : OPC
Date : 25-03-2015 to 01-04-2015

SL No	Name of Test	Results	Requirements as per
		Cement Sample	IS 12269-1987
1	Initial setting time	**135 min**	Shall not be less than 30 min
2	Final setting time	**245 min**	Shall not be more than 600 min
3	Fineness (by dry sieving on IS 90 micron sieve)	**2.40 %**	Not to exceed 10.0%
4	Soundness test(by Le-Chatelier's method)	**1.54 mm**	Shall not be more than 10 mm
5	Compressive strength a) 3 days (average of three results) b) 7 days (average of three results)	**30.50 N/ Sq mm** **43.10 N/Sq mm**	Shall not be less than 27 N/Sqmm Shall not be less than 37N/Sqmm

* As furnished by Client.
The Results relate only to the items tested.

Accepted

ವಿದ್ಯಾರಣ್ಯಪುರ ಉಪ ವಿಭಾಗ, ಯಲಹಂಕ ವಲಯ, ಬೃ. ಬೆಂ. ಮ. ಪಾ., ಬೆಂಗಳೂರು

G.R. HARISH
Professor
Department of Civil Engineering
Jnana Bharathi Compus
BANGALORE UNIVERSITY
Bangalore-560 056.

4/4/2015

Dr. MANJESH L
ME (Civil Engg) Ph D MISTE MIRC
Associate Professor
Department of Civil Engineering
Bangalore University Jnanabharathi Campus
BANGALORE- 560 056
e mail. manjeshl@yahoo.com

FOR QUALITY & EXCELLENCE IN HIGHER EDUCATION
Accredited by NAAC

BANGALORE UNIVERSITY
DEPARTMENT OF CIVIL ENGINEERING

Phone Off: 080-22961935 / 1946
E-mail: centrans9@gmail.com

JNANA BHARATHI
BANGALORE - 560 056

BUB/CTE/2014-15/

Date: 27-03-2015

1. TESTING OF COARSE AGGREGATES (40 mm):

Sub: Testing of Coarse Aggregates.

{Project*:Construction of rain water Harvesting (main tank) to Govt School Building at Doddabommasandra and Ramachandrapura Community Building at Ramachandrapura and Yelumandamma Badavane in Ward no. 10 Vidyaranyapura Sub-Division.}

Ref.: Letter No. Testing/BUB/2014-15, dated 24-03-2015

Sample supplied to lab by: Sri.K.Shankarreddy, Contractor, Bangalore.

Report required for: Assistant Executive Engineer, Vidyaranyapura Sub-Division. BBMP, Bangalore.

Table - 1.1 : SIEVE ANALYSIS :

IS Sieve Size, mm	Percentage passing	Requirements as per IS 383-1970 (Reaffirmed on 2007) % Passing	
	40 mm Sample	*Single size*	*Graded*
40mm	97.70	85-100	95 – 100
20mm	61.20	0 -20	30- 70
10mm	20.70	0 -5	10- 35
4.75mm	Nil	------	0 - 5

TABLE 1 2 :

SL No	Test conducted	Sample No	Results	Requirements as per IS:383-1970 & Test Conforms to IS 2386(Part I to IV) – 1963 (Reaffirmed on 2007)
1.	Flakiness Index	As above	16.90 %	Not to exceed 25 %
2.	Crushing value	----,,----	25.50%	Not to exceed 45 % for concrete other than for wearing surfaces and 30% for concrete for wearing surfaces

* As furnished by Client.

The Results relate only to the items tested.

Accepted

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ ಕಾರ್ಯಾಲಯ
ವಿದ್ಯಾರಣ್ಯಪುರ ಉಪ ವಿಭಾಗ
ಯಲಹಂಕ ವಲಯ.
ಬೃ. ಬೆಂ. ಮ. ಪಾ.. ಬೆಂಗಳೂರು-97

G.R. HARISH
Professor
Department of Civil Engineering
Jnana Bharathi Campus
BANGALORE UNIVERSITY
Bangalore-560 056.

27/3/2015

Dr. MANJESH .L
ME (Civil Engg) Ph D MISTE.MIRC
Associate Professor
Department of Civil Engineering
Bangalore University Jnanabharathi Campus
BANGALORE- 560 056
e-mail. manjeshl@yahoo.com

FOR QUALITY & EXCELLENCE IN HIGHER EDUCATION
Accredited by NAAC

BANGALORE UNIVERSITY
DEPARTMENT OF CIVIL ENGINEERING

Phone Off: 080-22961935 / 1946
E-mail: centrans9@gmail.com

JNANA BHARATHI
BANGALORE - 560 056

BUB/CTE/2014-15/

Date: 27-03-2015

1. TESTING OF FINE AGGREGATES :

Sub: Testing of Fine Aggregates.

{Project*:Construction of rain water Harvesting (main tank) to Govt School Building at Doddabommasandra and Ramachandrapura Community Building at Ramachandrapura and Yelumandamma Badavane in Ward no. 10 Vidyaranyapura Sub-Division.}

Ref.: Letter No. Testing/BUB/2014-15, dated 24-03-2015

Sample supplied to lab by: Sri.K.Shankarreddy, Contractor, Bangalore.

Report required for: Assistant Executive Engineer, Vidyaranyapura Sub-Division. BBMP, Bangalore.

TABLE - 1.1 : SIEVE ANALYSIS :

IS Sieve Size, mm	Percentage Passing	Specification as Per IS: 383-1970(Reaffirmed 2007) Percentage Passing			Remarks
		Zone-I	Zone-II	Zone -III	
04.75	97.90	90-100	90-100	90-100	The Sample Conforms to Grading **Zone-II**
02.36	82.20	60-95	75-100	85-100	
01.18	71.60	30-70	55-90	75-100	
600. mic	40.70	15-34	35-59	60-79	
300.mic	20.30	5-20	8-30	12-40	
150.mic	3.65	0-10	0-10	0-10	

TABLE 1.2 ;

Sl No	Test Conducted	Sample	Results	Requirements as Per IS. Specification IS :383-1970 (Reaffirmed 2007)
1	Silt Content	001	1.62 %	Not more than 8%
2.	Specific Gravity	----	2.60	-------

* As furnished by Client.

The Results relate only to the items tested.

Accepted

G.R. HARISH
Professor
Department of Civil Engineering
Jnana Bharathi Compus
BANGALORE UNIVERSITY
Bangalore-560 056.

27/03/2015

Dr. MANJESH .L
ME (Civil Engg) Ph D MISTE.MIRC
Associate Professor
Department of Civil Engineering
Bangalore University Jnanabharathi Campus
BANGALORE- 560 056.
e- mail. manjeshl@yahoo.com